## ITEM 6

# NORTH YORKSHIRE

### WEDNESDAY 19TH NOVEMBER 2014

### PUBLIC RIGHTS OF WAY MAINTENANCE UPDATE

#### 1.0 PURPOSE OF REPORT

- 1.1 To provide an update on maintenance work undertaken in the 2013/14 financial year.
- 2.0 BACKGROUND
  - 2.1 This report covers the period 1 April 2013 to 31 March 2014.

#### 3.0 FIGURES

3.1 The Following table shows the number of issues handled:

	lssues Logged	Issues Resolved
2012/13	2812	2636
2013/14	3632	3420
2014/15	2207	2253

- 3.2 The figures show an increase in newly reported issues of 29%. The number of resolved issues has jumped by 30%. The back log currently stands at 9118 (11<sup>th</sup> November 2014) an increase of 97 on the figure previously reported.
- 3.3 In Area 6 (Ryedale, Scarborough and Whitby), the Ryedale Rambler under took a complete survey of the network during the period 1114 new reports were logged which represents 30% of all the new reports received for the whole county.
- 3.4 Despite a reduction in staffing by 1 FTE over the year staff have continued to continuously improve performance.
- 3.5 Currently performance in 2014/15 is looking to match the previous year in both issues reported and issues resolved. We are currently managing this despite 2 FTE vacancies.
- 3.6 We are committed to reducing this back log by 15% in the current financial year; this will be as a result of the removal of poor and duplicate information.
- 3.7 The table below shows the breakdown of issue type since 2012/13

		Issue	s Logged		
Туре	2012/13	Туре	2013/14	Туре	2014/15 (6 Months)
Vegetation	670	Vegetation	795	Vegetation	561
Waymarking	319	Waymarking	503	Waymarking	231
Gate	264	Gate	361	Gate	167
Stile	237	Stile	346	Stile	151
Terrain	234	Terrain	254	Terrain	114
Signposting	170	Signposting	250	Signposting	111
Arable Paths	166	Sign roadside	172	Cross path	82
Obstacles	126	Cross path	143	Arable Paths	59
Sign roadside	110	Obstacles	132	Sign roadside	53
Cross path	101	Arable Paths	129	Obstacles	41
	•	Issues	Resolved		
Туре	2012/13	Туре	2013/14	Туре	2014/15
	2012/10				(6 Months)
Vegetation	651	Vegetation	769	Vegetation	442
Waymarking	307	Waymarking	481	Waymarking	256
Gate	280	Stile	353	Gate	196
Stile	237	Gate	246	Stile	187
Signposting	177	Terrain	249	Cross path	118
Terrain	158	Signposting	204	Signposting	107
Arable Paths	151	Cross path	168	Terrain	97
Sign roadside	123	Sign roadside	124	Sign roadside	53
Cross path	119	Obstacles	116	Arable Paths	44
Obstacles	90	Arable Paths	114	Obstacles	40

- 3.8 As can be seen the first 6 issues reported have remained unchanged with vegetation being the most reported and the most resolved issue.
- 3.9 The tables below represent the age profile of the back log on the 8<sup>th</sup> October 2014 and the second table 9<sup>th</sup> August 2013.

Year		Outstand	ing Issues	10/14
	High	Medium	Low	Total
2014/15	6	265	638	909
2013/14	4	227	906	1137
2012/13	3	161	552	716
2011/12	0	109	523	632
2010/11	3	116	390	509
2009/10	1	85	345	431
2008/09	0	122	570	692
2007/08	2	117	654	773
2006/07	2	144	1081	1227
2005/06	0	181	1129	1310
2004/05	0	68	354	422
2003/04	2	59	190	251
Older	3	74	220	297
			Total	9306

Year		Outstand	ing Issues	08/13
	High	Medium	Low	Total
2013/14	0	153	487	640
2012/13	5	234	793	1032
2011/12	0	163	674	837
2010/11	4	141	469	614
2009/10	1	114	409	524
2008/09	0	153	727	880
2007/08	1	130	682	813
2006/07	2	169	1236	1407
2005/06	1	201	1250	1452
2004/05	1	77	387	465
2003/04	2	65	218	285
Older	3	85	244	332
			Total	9281

### 4.0 BRIDGES

4.1 A total of 60 repairs took place; this represents an increase on the previous year of 32. These are shown in Appendix 1.

Asset No.		District	Parish	Grid Ref
10.21/2986	FP	Hambleton	Burrill	42400 4869
10.014/7029	BW	Hambleton	Birkby	42621 46241
10.133/364	FP	Hambleton	Snape	42855 48446
15.130/1045	FP	Harrogate	Thornthwaite with	41789 45905
			Padside	
15.63/337	FP	Harrogate	Ilton-cum-Pott	41894 47921
15.16/271	FP	Harrogate	Brearton	43213 46064
15.46/3553	FP	Harrogate	Goldsborough	43829 45805
15.118/7408	BR	Harrogate	Sicklinghall	43649 44606
20.37/1046	FP	Richmondshire	Hudswell	41445 49955
25.49/4101	FP	Ryedale	Hovingham	46765 47736
25.50/791	FP	Ryedale	Howsham	47371 46128

4.2 The following bridges have been replaced in 2014/15

#### 5.0 PLOUGHING AND CROPPING

- 5.1 The process of bi annual surveys continued into its seventh year. Volunteers continue to undertake the initial survey with follow up by Rangers where failures are identified.
- 5.2 A number of routes were added to the programme and the breakdown by district follows:

District	Routes on List	No. Routes Surveyed	Pass	Fail	Pass Rate (%)	Comparison with Previous Survey (%)
Craven	2	2	2	0	100	50
Harrogate	61	29	15	14	52	17
Hambleton	135	54	18	36	33	21
Selby	85	19	6	13	32	-8
Richmond	25	44	19	25	43	17
Ryedale	75	51	27	24	53	31
Scarborough	6	6	0	6	0	0


5.3 Due to staff changes and illness the summer survey did not take place.

#### 6.0 PROJECTS

- 6.1 A number of significant projects were also completed during the year.
- 6.2 Working in partnership with Highways Asset management the rights of way team took the lead in carrying out clearance work with volunteers on a number of unclassified roads.
- 6.3 Working with volunteers the Ripon Rowel promoted route guide has been rewritten and has been re-launched.
- 6.4 The extension to the Nidderdale Greenway has been completed providing a traffic free cycling link from Ripley to the quite lane network and beyond. This work was undertaken in partnership with SUSTRANS and DFT.
- 6.5 A group of volunteers have been trained and have started to survey all of the bridge stock identified on CAMS.

### 7.0 NETWORK CONDITION

7.1 Each time a route is visited by a member of the team, and in future by volunteers, as part of maintaining the network, the condition is assessed against the BVPI 178 criteria and recorded allowing a rolling indication of condition to be produced.



### 8.0 CONCLUSIONS

- 8.1 This work contributes to the enjoyment of our network and the improvement is highlighted in the following power-point presentation.
- 8.2 It is recommended that members receive this report for information.

<u>CONTACT OFFICER</u>: lain Burgess Senior Ranger 01609 532894

01609 7807		e & Countryside Service, Co			5, 527 6741		
				Issue Inv	ventory Report		
Admin Gro	up: Crave	en					
Admin Area:	Cra - Burton-i	n-Lonsdale					
<u>ssue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
34200	02/04/2008	Bridge/Replace	05.9/3379	Furniture	SD65437226	High	Resolved
51188	02/07/2013	Bridge/Repair	05.9/3379	Furniture	SD65447228	High	Resolved
Admin Area T	otal	2					
Admin Area:	Cra - Hellifield	ł					
<u>ssue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
13338	14/02/2011	Bridge/Replace	05.25/3290	Furniture	SD85285636	High	Resolved
Admin Area T	otal	1					
Admin Area:	Cra - Kildwick	(					
ssue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52466	30/10/2013	Bridge Obstructed	05.27/5731	Furniture	SE02954569	Low	Resolved
Admin Area T	otal	1					
Admin Area:	Cra - Sutton-i	n-Craven					
ssue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
9392	22/11/2012	Bridge Obstructed	05.39/3/2	Path/Link	SE00284449	Low	Resolved

APPENDIX 1

Report Crea 11/1 <sup>,</sup>	ation Date 1/2014		North Ye	orkshi	re County Council		
Public Right 01609 7807		e & Countryside Service, C	County Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area T	otal	1					
Admin Group	Total	5					
Admin Grou	up: Hamb	leton					
Admin Area:	Ham - Aindert	by Steeple					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52063	02/10/2013	Bridge/Replace	10.3/9/1	Path/Link	SE33219004	[N/A]	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Borrow	by					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
50325	02/05/2013	Bridge/Repair	10.16/2799	Furniture		Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Crayke						
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
50527	22/05/2013	Bridge/Replace	10.33/182	Furniture	SE56947201	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Easby						
<u>Issue Code</u>	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
Report genera	ted from Countr	yside Access Managemen	t System (CAMS)			Page 2 of 19 exeGe	esIS SDM Ltd.

Report Crea 11/1	ition Date 1/2014		North Y	orkshi	re County Council		
Public Right 01609 7807		e & Countryside Service, Count	ty Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
47616	15/05/2012	Bridge/Repair	10.39/2/2	Path/Link	NZ57400952	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Easing	wold					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
50041	20/03/2013	Bridge/Repair	10.40/5076	Furniture	SE53726908	Medium	Resolved
51721	04/09/2013	Bridge/Repair	10.40/5076	Furniture	SE53736906	Medium	Resolved
Admin Area T	otal	2					
Admin Area:	Ham - Exelby,	Leeming and Newton					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
48578	13/08/2012	Bridge/Repair	10.47/7864	Furniture	SE28768925	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Ingleby	Greenhow					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
38358	04/06/2009	Bridge/Replace	10.75/3/1	Path/Link	NZ57310724	Medium	Resolved
38361	04/06/2009	Bridge/Replace	10.75/3/1	Path/Link	NZ57230730	Medium	Resolved
42852	09/12/2010	Bridge/Repair	10.75/3872	Furniture	NZ58360714	Low	Resolved
Admin Area T	otal	3					

Page 3 of 19 exeGesIS SDM Ltd.

Report Creation Date 11/11/2014		North Yo	North Yorkshire County Council				
Public Right 01609 7807		e & Countryside Service, Co	unty Hall Northallerton, I	North Yorkshir	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area:	Ham - Kirby W	liske					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<b>Priority</b>	<u>Status</u>
51967	18/09/2013	Bridge Obstructed	10.82/2966	Furniture	SE35858554	High	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Little A	yton					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<b>Priority</b>	<u>Status</u>
51641	28/08/2013	Bridge/Repair	10.92/4509	Furniture	NZ56971013	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Morton	on Swale					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
50199	10/04/2013	Bridge/Repair	10.100/2633	Furniture	SE32988922	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Ham - Nether	Silton					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
36271	12/09/2008	Bridge/Replace	10.102/7952	Furniture	SE45179130	Medium	Resolved
Admin Area T	otal	1					

#### **Report Creation Date**

11/11/2014

## **North Yorkshire County Council**

Public Rights of Way, Waste & Countryside Service, County Hall Northallerton, North Yorkshire, DL7 8AH 01609 780780



**Issue Inventory Report** 

Admin Area:	Ham - Northal	lerton					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
50676	10/06/2013	Bridge/Repair	10.110/7773	Furniture	SE39129344	High	Resolved
50865	26/06/2013	Bridge/Repair	10.110/6277	Furniture	SE36469420	High	Resolved
Admin Area T	<b>Total</b>	2					
Admin Area:	Ham - Potto						
ssue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
21861	31/01/2006	Bridge/Repair	10.118/4189	Furniture	NZ47510534	High	Resolved
Admin Area T	<b>Total</b>	1					
Admin Area:	Ham - Rand G	range					
ssue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
01223	10/12/1999						
	10/12/1000	Bridge/Repair	10.119/2979	Furniture	SE25598951	Medium	Resolved
		Bridge/Repair	10.119/2979	Furniture	SE25598951	Medium	Resolved
Admin Area T		1	10.119/2979	Furniture	SE25598951	Medium	Resolved
Admin Area T	<b>Total</b>	1	10.119/2979 	Furniture	SE25598951 Grid Reference	Medium Priority	Resolved
Admin Area 1 Admin Area:	Fotal Ham - Seamer	1 <u>Type</u>					

Report generated from Countryside Access Management System (CAMS)

Page 5 of 19 exeGesIS SDM Ltd.

Report Creation Date 11/11/2014		North Yorkshire County Council					
Public Rights 01609 78078		e & Countryside Service, Cou	nty Hall Northallerton, I	North Yorkshir	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area:	Ham - South F	Kilvington					
Issue Code	Log Date	Type	Link Code	Link Type	Grid Reference	<b>Priority</b>	<u>Status</u>
51827	09/09/2013	Bridge/Repair	10.135/7277	Furniture	SE42448415	High	Resolved
Admin Area To	otal	1					
Admin Area:	Ham - Sowerb	у					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52657	22/11/2013	Bridge/Repair	10.137/7197	Furniture	SE43338159	High	Resolved
Admin Area To	otal	1					
Admin Area:	Ham - Stilling	ton					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
53447	20/02/2014	Bridge/Repair	10.139/657	Furniture	SE58716877	Medium	Resolved
Admin Area To	otal	1					
Admin Area:	Ham - Sutton	under Whitestonecliffe					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
49148	19/10/2012	Bridge/Repair	10.142/8078	Furniture	SE48768283	Medium	Resolved
Admin Area To	otal	1					

r, Waste & Countryside Service,	County Hall Northallerton, I		e, DL7 8AH ventory Report		
		Issue Inv	ventory Report		
)ate Type					
	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
0/2013 Bridge/Repair	10.146/6147	Furniture	SE41629602	Low	Resolved
1					
Thirkleby High & Low with Osg	godby				
Date <u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
5/2013 Bridge/Repair	10.147/6/1	Path/Link	SE47457875	High	Resolved
1					
Thirsk					
Date <u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
6/2012 Bridge/Repair	10.150/7695	Furniture	SE42938237	High	Resolved
9/2013 Bridge/Repair	10.150/567	Furniture	SE42378425	High	Resolved
2					
Tollerton					
Date <u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
9/2013 Bridge/Repair	10.160/764	Furniture	SE50606397	Medium	Resolved
1					
	/2013 Bridge/Repair 1 Thirkleby High & Low with Osg ate Type /2013 Bridge/Repair 1 Thirsk ate Type /2012 Bridge/Repair /2013 Bridge/Repair 2 follerton ate Type /2013 Bridge/Repair	/2013       Bridge/Repair       10.146/6147         1       1         hirkleby High & Low with Osgodby       Ink Code         /2013       Bridge/Repair       10.147/6/1         1       1       1         hirsk       I       Ink Code         /2013       Bridge/Repair       10.147/6/1         1       1       Ink Code         /2012       Bridge/Repair       10.150/7695         /2013       Bridge/Repair       10.150/567         2       Ink Code       Ink Code         /2013       Bridge/Repair       10.150/7695         /2013       Bridge/Repair       10.160/764	/2013       Bridge/Repair       10.146/6147       Furniture         1       1         Initkleby High & Low with Osgodby         ate Type Link Code 10.147/6/1       Link Type         /2013       Bridge/Repair       10.147/6/1       Path/Link         1       1       1       1         hirsk       Link Code       Link Type       Furniture         /2012       Bridge/Repair       10.150/7695       Furniture         /2013       Bridge/Repair       10.150/567       Furniture         /2013       Bridge/Repair       10.150/567       Furniture         /2013       Bridge/Repair       10.150/7695       Furniture         /2013       Bridge/Repair       10.150/7695       Furniture         /2013       Bridge/Repair       10.150/7695       Furniture         /2013       Bridge/Repair       10.160/764       Furniture	Image: Network in the second secon	V2013         Bridge/Repair         10.146/6147         Furniture         SE41629602         Low           1         1         Image: Constraint of the second of the seco

Page 7 of 19 exeGesIS SDM Ltd.

Report Crea 11/1	ation Date 1 <b>1/2014</b>	North Ye	orkshi				
Public Righ 01609 7807	-	e & Countryside Service,	County Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area:	Ham - Warlab	у					
ssue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
38364	04/06/2009	Bridge/Replace	10.163/2627	Furniture	SE33248946	Medium	Resolved
Admin Area T	<b>Fotal</b>	1					
dmin Area:	Ham - West H	arlsey					
ssue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
3514	27/02/2014	Bridge/Repair	10.166/6686	Furniture	SE40139754	Medium	Resolved
dmin Area T	ſotal	1					
dmin Area:	Ham - Youlto	n					
sue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
0842	24/06/2013	Bridge/Replace	10.176/812	Furniture	SE49696370	Medium	Resolved
dmin Area T	<b>Fotal</b>	1					
dmin Group	Total	31					
dmin Gro	up: Harro	ogate					
dmin Area:	Har - Askwith						
sue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
86461	07/10/2008	Bridge/Repair	15.6/5130	Furniture	SE17125209	Medium	Resolved
	atod from Count	ryside Access Manageme	nt Suctom (CAMS)			Page 8 of 19 exeGe	esIS SDM Ltd.
epoir genera		i yside Access Manayeme					

Report Crea 11/1	ation Date 1/2014		North Y	orkshi	re County Council		
Public Righ 01609 7807		e & Countryside Service, C	County Hall Northallerton,	North Yorkshin	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area 1	otal	1					
Admin Area:	Har - Bewerle	y					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
47208	23/03/2012	Bridge/Replace	15.9/253	Furniture	SE15296428	High	Resolved
Admin Area 1	otal	1					
Admin Area:	Har - Bishop T	Fhornton					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
39370	23/09/2009	Bridge/Replace	15.13/259	Furniture	SE25746413	High	Resolved
33077	04/01/2008	Bridge/Repair	15.13/9106	Furniture	SE24546485	Low	Resolved
Admin Area 1	otal	2					
Admin Area:	Har - Dacre						
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
51759	09/09/2013	Bridge/Replace	15.29/9460	Furniture		High	Resolved
52318	31/05/2013	Bridge/Replace	15.29/9462	Furniture	SE17616409	High	Resolved
53083	02/01/2014	Bridge/Repair	15.29/282	Furniture	SE18576407	High	Resolved
Admin Area 1	otal	3					

Page 9 of 19 exeGesIS SDM Ltd.

Public Rights		e & Countryside Service, C	ounty Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
dmin Area:	Har - Denton						
<u>sue Code</u>	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
5122	14/07/2008	Bridge/Replace	15.30/19/1	Path/Link	SE14624949	Low	Resolved
dmin Area To	otal	1					
lmin Area:	Har - Fearby						
<u>sue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
459	20/05/2012	Bridge/Replace	15.38/8952	Furniture	SE19588075	High	Resolved
274	07/02/2011	Bridge/Repair	15.38/8944	Furniture	SE19878092	Medium	Resolved
lmin Area To	otal	2					
lmin Area:	Har - Fewston						
sue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
259	19/09/2005	Bridge/Repair	15.41/9292	Furniture	SE19895534	Low	Resolved
dmin Area To	otal	1					
lmin Area:	Har - Great Tir	nble					
sue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
705	14/07/2009	Bridge/Replace	15.50/307	Furniture	SE17885257	Medium	Resolved
052	11/07/2013	Bridge/Replace	15.50/5251	Furniture	SE17475404	Medium	Resolved
	ted from Countr	vside Access Managemen	t System (CAMS)			Page 10 of 19 exeGe	elS SDM i td

North Yorkshire County Council

Report Creation Date

11/11/2014

1953

Report Crea 11/1	ation Date 11/2014		North Ye	orkshi	re County Council		
Public Righ 01609 7807		e & Countryside Service, C	ounty Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area	Total	2					
Admin Area:	Har - Harroga	te Borough					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52965	23/12/2013	Bridge/Repair	15.54/9046	Furniture	SE28955124	Medium	Resolved
43966	10/05/2011	Bridge/Repair	15.54/9159	Furniture	SE30595595	Low	Resolved
Admin Area	Total	2					
Admin Area:	Har - Hartwith	cum Winsley					
<u>Issue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
41838	04/01/2000	Bridge/Replace	15.55/316	Furniture	SE22356451	High	Resolved
Admin Area	Total	1					
Admin Area:	Har - Healey						
<u>Issue Code</u>	Log Date	Type	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
48997	01/10/2012	Bridge/Repair	15.57/17/1	Path/Link	SE15408097	Medium	Resolved
Admin Area	Total	1					
Admin Area:	Har - Ilton cur	n Pot					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52685	20/11/2013	Bridge Obstructed	15.63/338	Furniture	SE18657871	Medium	Resolved
Bonort concer	atad from Count	yside Access Managemen				Page 11 of 19 exeGe	sIS SDM Ltd.
Report genera		youe Access Managemen				-	me: xaMaintInventRot

1

Report Creation Date 11/11/2014			North Y				
Public Right 01609 7807		e & Countryside Service,	County Hall Northallerton,	North Yorkshire	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area T	otal	1					
Admin Area:	Har - Kearby	with Netherby					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52829	11/12/2013	Bridge/Repair	15.64/8968	Furniture	SE32784692	Low	Resolved
Admin Area T	otal	1					
Admin Area:	Har - Killingha	all					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
14300	12/11/1999	Bridge/Repair	15.65/5/1	Furniture	SE29125885	High	Resolved
Admin Area T	otal	1					
Admin Area:	Har - Kirkby M	lalzeard					
Issue Code	Log Date	Type	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
35666	28/07/2008	Bridge/Repair	15.70/172	Furniture	SE21287318	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Har - Lavertor	1					
Issue Code	Log Date	Type	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
53402	12/02/2014	Bridge/Repair	15.75/9472	Furniture	SE22417264	Medium	Resolved
Admin Area To	otal	1					

Page 12 of 19 exeGesIS SDM Ltd.

#### **Report Creation Date**

11/11/2014

## **North Yorkshire County Council**

Public Rights of Way, Waste & Countryside Service, County Hall Northallerton, North Yorkshire, DL7 8AH 01609 780780



Issue Inventory Report

Admin Area:	Har - Leathley	,					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
50138	02/04/2013	Bridge Obstructed	15.76/9236	Furniture	SE23034798	Medium	Resolved
53569	07/03/2014	Bridge/Repair	15.76/3207	Furniture	SE23084727	Medium	Resolved
Admin Area T	otal	2					
Admin Area:	Har - Marking	ton with Wallerthwaite					
<u>Issue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
43117	24/11/2010	Bridge/Repair	15.86/9383	Furniture	SE29666559	Low	Resolved
Admin Area T	otal	1					
Admin Area:	Har - Marton o	cum Grafton					
<u>Issue Code</u>	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
53292	31/01/2014	Bridge/Repair	15.87/7/1	Path/Link	SE42126231	Low	Resolved
Admin Area T	otal	1					
Admin Area:	Har - Menwith	with Darley					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52811	09/12/2013	Bridge/Repair	15.91/3752	Furniture	SE21155971	High	Resolved

Report generated from Countryside Access Management System (CAMS)

Page 13 of 19 exeGesIS SDM Ltd.

Report Creation Date 11/11/2014			North Yo	orkshi			
Public Right 01609 7807	-	e & Countryside Service, Co	unty Hall Northallerton,	North Yorkshir	e, DL7 8AH		
				Issue Inv	ventory Report		
dmin Area:	Har - North Ri	gton					
sue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
0373	03/02/2010	Bridge/Replace	15.101/14/1	Path/Link	SE29764937	Medium	Resolved
dmin Area T	otal	1					
dmin Area:	Har - Scotton						
sue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
6848	05/10/2006	Bridge/Repair	15.115/8491	Furniture	SE33186015	High	Resolved
dmin Area T	otal	1					
dmin Area:	Har - Spoffort	h with Stockeld					
ssue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
3243	24/01/2014	Bridge Obstructed	15.122/10/1	Path/Link	SE35454992	Medium	Resolved
2452	28/10/2013	Bridge/Replace	15.122/9020	Furniture	SE35915051	Low	Resolved
dmin Area T	otal	2					
dmin Area:	Har - Staveley	,					
ssue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
9253	21/10/2005	Bridge/Replace	15.124/8/2	Path/Link		Medium	Resolved
37222	08/12/2008	Bridge/Replace	15.124/3491	Furniture	SE36576392	Medium	Resolved
Report genera	ated from Countr	yside Access Management	System (CAMS)			Page 14 of 19 exeGe	sIS SDM Ltd

Report Creati 11/11/			North Yo	orkshi	re County Council		
Public Rights 01609 78078		e & Countryside Service, Co	unty Hall Northallerton, I	North Yorkshir	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area To	tal	2					
Admin Area:	Har - Tockwith	1					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
43805	18/04/2011	Bridge/Repair	15.135/4770	Furniture	SE47505418	Medium	Resolved
Admin Area To	tal	1					
Admin Group 1	Fotal	34					
Admin Grou	p: Richn	nondshire					
Admin Area:	Rich - Consta	ble Burton					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
43038	10/01/2011	Bridge/Repair	20.16/1064	Furniture	SE17509058	Medium	Resolved
Admin Area To	tal	1					
Admin Area:	Rich - Scortor	1					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
32181	04/10/2007	Bridge/Repair	20.58/7254	Furniture	NZ25420018	High	Resolved
Admin Area To	tal	1					
Admin Group 1	Fotal	2					
Admin Grou	p: Ryeda	ale					

Page 15 of 19 exeGesIS SDM Ltd.

#### **Report Creation Date**

11/11/2014

### **North Yorkshire County Council**

Public Rights of Way, Waste & Countryside Service, County Hall Northallerton, North Yorkshire, DL7 8AH 01609 780780



**Issue Inventory Report** 

Admin Area:	Rye - Amplefo	rth					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
50169	03/04/2013		25.6/1926	Furniture	SE60277812	Medium	Resolved
50397	10/05/2013	Bridge/Repair	25.6/7/1	Path/Link	SE58897701	Medium	Resolved
Admin Area To	otal	2					
Admin Area:	Rye - Crambe						
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
50213	10/04/2013	Bridge/Repair	25.25/2044	Furniture	SE74496439	Medium	Resolved
50735	17/06/2013	Bridge/Repair	25.25/2044	Furniture	SE74496437	Medium	Resolved
Admin Area To	otal	2					
Admin Area:	Rye - Habton						
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
07055	08/07/2003	Bridge/Replace	25.41/2181	Furniture	SE75027813	Low	Resolved
Admin Area To	otal	1					
Admin Area:	Rye - Huttons	Ambo					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
47312	10/04/2012	Bridge/Repair	25.51/2348	Furniture	SE73876911	Low	Resolved
Report generat	ed from Countr	yside Access Management System	(CAMS)			Page 16 of 19 exeGe	sIS SDM Ltd.

Report Creation Date 11/11/2014	I	North Y	orkshi	re County Council		
Public Rights of Way, Waste of 01609 780780	& Countryside Service, County H	all Northallerton,	North Yorkshire	e, DL7 8AH		
			Issue Inv	ventory Report		
Admin Area Total	1					
Admin Area: Rye - Kirkbymo	oorside					
Issue Code Log Date	Type	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
45231 11/08/2011	Bridge/Repair	25.54/28/1	Path/Link	SE68858648	Medium	Resolved
Admin Area Total	1					
Admin Area: Rye - Nunningt	on					
Issue Code Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
49524 18/12/2012 I	Bridge/Repair	25.71/373	Furniture	SE65627960	Medium	Resolved
Admin Area Total	1					
Admin Area: Rye - Terringto	n with Wiganthorpe					
Issue Code Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52201 11/10/2013 I	Bridge Obstructed	25.94/3355	Furniture	SE67867188	High	Resolved
Admin Area Total	1					
Admin Area: Rye - Wharram						
Issue Code Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52574 14/11/2013	Bridge/Repair	25.108/45	Furniture	SE86116455	High	Resolved
Admin Area Total	1					
~	nida Aaaaaa Managamant System				Dage 17 of 10 even	

Page 17 of 19 exeGesIS SDM Ltd.

Report Creation Date 11/11/2014			North Y				
Public Rights 01609 78078		e & Countryside Service, C	ounty Hall Northallerton,	North Yorkshin	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area:	Rye - Wintring	ham					
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52573	14/11/2013	Bridge Obstructed	25.112/413	Furniture	SE87827330	High	Resolved
Admin Area To	otal	1					
Admin Group	Total	11					
Admin Grou	p: Scarb	orough					
Admin Area:	Scar - East Ay	ton					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
52847	12/12/2013	Bridge/Repair	30.6/206	Furniture	SE99308417	Medium	Resolved
Admin Area To	tal	1					
Admin Group	Total	1					
Admin Grou	p: Selby						
Admin Area:	Sel - Balne						
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
37281	15/12/2008	Bridge/Repair	35.3/2355	Furniture	SE58781880	Medium	Resolved
Admin Area To	tal	1					

Report Creation Date 11/11/2014		North Yorkshire County Council					
Public Right 01609 7807		e & Countryside Service,	County Hall Northallerton,	North Yorkshir	e, DL7 8AH		
				Issue Inv	ventory Report		
Admin Area:	Sel - Colton						
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	Priority	<u>Status</u>
52670	25/11/2013	Bridge/Repair	35.24/1641	Furniture	SE54904426	Low	Resolved
Admin Area T	otal	1					
Admin Area:	Sel - Gatefort	h					
Issue Code	Log Date	Type	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
49659	14/01/2013	Bridge/Repair	35.30/2899	Furniture	SE56192839	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Sel - Hillam						
Issue Code	Log Date	Туре	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
51742	06/09/2013	Bridge/Repair	35.37/1766	Furniture	SE50592898	Medium	Resolved
Admin Area T	otal	1					
Admin Area:	Sel - Kellingto	on					
Issue Code	Log Date	<u>Type</u>	Link Code	Link Type	Grid Reference	<u>Priority</u>	<u>Status</u>
53084	10/01/2014	Bridge/Repair	35.41/12/1	Path/Link	SE55962384	High	Resolved
Admin Area T	otal	1					
Admin Group	Total	5					
Report Total		89					
		nucida Anna Man	10 1 (0.110)				

Page 19 of 19 exeGesIS SDM Ltd.