

From: [REDACTED]
To: [Chris Bourne](#)
Cc: [REDACTED]
Subject: Whitby Cliff Lift
Date: 24 January 2026 20:14:32
Attachments: [image001.png](#)
[image002.png](#)
[image003.png](#)
[image004.png](#)
[image005.png](#)
[image006.png](#)
[image007.png](#)

[OFFICIAL]

Hi Chris,

As you know, we visited the Cliff Lift on Wednesday.

The focus of the visit was to look at whether there was further evidence of water ingress since we visited in August following the wetter months over winter. Overall, conditions appeared similar to those in August. However, it was noted that there was one isolated source of inflow at the top section of the shaft. The cause of this is unclear and we recommend that it should be further investigated. The previous recommendations from the earlier visit remain unchanged.

I would like to reiterate that this is a high-level view based on our short visits, rather than an in-depth analysis, and that that our views and recommendations should be subject to a detailed professional review.

Regards,

[REDACTED]

Manager Woodsmith
Crop Nutrients



E [REDACTED]

CROP NUTRIENTS
Resolution House, Lake View, Scarborough YO11 3ZB
United Kingdom

[REDACTED]
www.angloamerican.com

A member of the Anglo American plc group



CONFIDENTIALITY CAUTION: This email (including any attachments) is intended only for the use of the individual or entity to whom it is addressed and may contain confidential information and be protected by legal privilege. Please notify us immediately by return email if you have received this email in error and delete this email and any attachments. If you are not the intended recipient, dissemination, disclosure and use of any information herein is prohibited. PRIVACY NOTICE: Anglo American processes personal data in accordance with applicable data privacy laws. For more information please see our [Privacy Policy](#).