


C2/10/02487/CCC


Extraction and processing of sand and gravel including the construction of a site access, conveyors, bridges, associated plant and machinery with restoration to agriculture, nature conservation and wetland at Killerby Sand and Gravel Quarry, Killerby, North Yorkshire, DL10 7PY



















Phase 1 (extract from drwg no. NT10306/12/Figure 3.3 rev A, dated 4th March 2015)




Phase 2 (extract from drwg no. NT10306/12/Figure 3.4 rev A, dated 4th March 2015)



Phase 3 (extract from drwg no. NT10306/12/Figure 3.5 rev A, dated 4th March 2015)

Proposed sand & gravel quarry at Killerby 3.8m wale Plantation 4C 5.7m Shingle 3.9m 4D 4.8m 4B **Killerby** 5.0m **East** 4E 5.4m 7.6m Bund /17/ Bund 16 S\$ Capacity for 4B TS Capacity for 4B -48,000m 34,000m Bund 3 Bund 2 TS Capacity for 1A SS Capacity for 1A, 2A, 3A and 3B -2A, 3A and 3B 27,500m³ 70,000m³

Phase 4 (extract from drwg no. NT10306/12/Figure 3.6 rev A, dated 4th March 2015)




Phase 5 (extract from drwg no. NT10306/12/Figure 3.7 rev A, dated 4th March 2015)





(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint (a stated distance of 2.5 kilometres), taken from a local road, east of Bolton-on-Swale village, the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 2

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint (a stated distance of 850 metres), between the village of Ellerton and the B2671, the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.





(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint at Langton Bridge over the River Swale (a stated distance of 1.7 kilometres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 4

(extract from submitted Landscape & Visual Impact Assessment)



From this viewpoint at the north end of Greengate Lane (a stated distance of 500 metres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 5

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint near Green Gate Farm (a stated distance of 350 metres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 6

(extract from submitted Landscape & Visual Impact Assessment)



From this viewpoint along Lumley Lane, near Melton House (a stated distance of 800 metres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 7

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint at the junction of Low Street and the A1(T) (on the site boundary), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.




Viewpoint No. 8

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint taken to the west of Great Fencote village and north of Little Fencote (a stated distance of 3.6 kilometres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 9

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint taken from Tickergate Lane (a stated distance of 1.65 kilometres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 10

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint taken from Leases Lane on the opposite side (west) of the A1(T) (a stated distance of 700 metres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.




Viewpoint No. 11

(extract from submitted Landscape & Visual Impact Assessment)




From this viewpoint taken from Swale Lane on the eastern edge of Catterick (a stated distance of 2.3 kilometres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.



Viewpoint No. 12

(extract from submitted Landscape & Visual Impact Assessment)



From this viewpoint taken from Catterick Lane on the opposite (west) side of the A1(T) (a stated distance of 1.5 kilometres), the LVIA found there to be no views capable of being gained either of the mineral development or of the restored land.

RESTORATION **MASTERPLAN**

submitted 'Restoration Masterplan' (drwg ref. no. NT10306/12/fig 3.8, rev H, dated 7th July 2016)