



Driver & Vehicle
Standards
Agency

MOT test certificate

① Vehicle identification number

ZVW301782885

②a) Registration number ②b) Country of registration

LY63XTK

GB

Make and model

TOYOTA PRIUS

⑤ Vehicle category

④ Mileage

Mileage history

72,200 miles

55,428 miles

13.09.2023

58,031 miles

14.10.2022

⑦ Pass with defects

⑥ Repair as soon as possible (minor defects)

- Registration plate lamp insecure Nearside [4.7.1 (c) (i)]

Monitor and repair if necessary (advisories)

- Tyre worn close to legal limit/worn on edge Nearside Front (2mm + bald edges) [5.2.3 (e)]
- Tyre worn close to legal limit/worn on edge Nearside Rear (3mm) [5.2.3 (e)]

③b) Date of the test

07.08.2024

⑧ Expiry date

06.08.2025

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 07.07.2025.

③a) Location of the test

AIREDALE BUSINESS CENTRE, KEIGHLEY ROAD, SKIPTON, BD23 2TZ

⑨ Testing organisation and inspector name

**V102805 MMC
B. P. BATTY**

MOT test number

464166916434

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.



Chassis No: 782885	Inspection Form Reference:		Vehicle type: <input type="checkbox"/> Hackney carriage <input checked="" type="checkbox"/> Private Hire
Vehicle Registration: LY63 XTK	Make and Model: TOYOTA PRIUS	Year of Manufacture:	
Plate number: 3SA	Mileage: 72200	Colour: PINK	
Driver Name: ? A. NAWAZ	Badge Number: ? 248A		

All hackney carriage and private hire vehicles must be maintained to no less than the standards set out in the DVSA publication 'MOT Inspection Manual – Private Passenger and Light Commercial Vehicle Testing', ISBN 978-0-9549352-5-2. Failure to meet such standards would result in the inspection being failed.
In addition, the inspection should be failed if any of the reasons below apply.

Item Tested	Pass (✓)	Fail (x)	Reasons for Failure (see overleaf for guidance)
MOT			
MOT requirements	///	✓	Failed MOT
Lighting Equipment			
Front and rear lamps	///		
Headlamps	///		
Stop lamps	///		
Rear reflectors	///		
Direction indicators	///		
Steering and suspension			
Steering control	///		
Steering mechanism/system	///		
Power steering	///		
Transmission	///		
Wheel bearings	///		
Front suspension	///		
Rear suspension	///		
Shock absorbers	///		
Brakes			
Controls/ABS warning system	///		
Condition of service brake system	///		
Condition of parking brake system	///		
Service brake performance	///		
Parking brake performance	///		
Tyres and wheels			
Tyre type	///		Please complete the information below
Tyre condition (including spare)	///		N/S/F <input type="checkbox"/> 2 N/S/R <input type="checkbox"/> 3 SPARE <input checked="" type="checkbox"/>
Tread Depth of each tyre	///		O/S/F <input type="checkbox"/> 6 O/S/R <input type="checkbox"/> 4
Road wheels	///		
Seats and Seat belts			
How many seats does the vehicle have?	///		4 passengers
Mountings	///		
Condition	///		
General			
Driver's view of the road and mirrors	///		Front ORS bulbs was cold
Horn	///		
Exhaust system	///		
Fuel system	///		
Exhaust emissions	///		
Body interior	///		
Luggage space	///		
First aid kit	///		

Meter - test and seal	<input checked="" type="checkbox"/>		
Licence front and rear plates & doors	<input checked="" type="checkbox"/>		
Roof sign & For Hire sign (HC only)	<input checked="" type="checkbox"/>		
Body exterior	<input checked="" type="checkbox"/>		
Doors	<input checked="" type="checkbox"/>		
Seats	<input checked="" type="checkbox"/>		
Electrical wiring and equipment	<input checked="" type="checkbox"/>		
Speedo	<input checked="" type="checkbox"/>		
Oil and water leaks	<input checked="" type="checkbox"/>		
Signage	<input checked="" type="checkbox"/>		
No Smoking signs on display?	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No		No DRIVERS ID DISPLAYED
Advertising on or in vehicle?	<input checked="" type="checkbox"/> Yes / <input type="checkbox"/> No		


Does the vehicle appear to be adapted to be wheelchair accessible?	Yes	<input checked="" type="checkbox"/> No
If yes to the above, does the vehicle have a mechanical lift?	Yes	<input checked="" type="checkbox"/> No

Item Tested	Standards of Inspection - Possible reasons for failure
Lighting Equipment	
Front and rear lamps	Lights inoperable or of insufficient intensity. Incorrect bulbs fitted. Lamps not properly aligned. Lamp flickers when tapped lightly by hand.
Headlamps	
Stop lamps	
Rear reflectors	
Direction indicators	
Steering and suspension	
Steering control	Inoperable, worn or faulty steering or suspension. Jagged edges on steering wheel rim.
Steering mechanism/system	
Power steering	
Transmission	
Wheel bearings	
Front suspension	
Rear suspension	
Shock absorbers	
Brakes	
Controls/ABS warning system	Any of the systems do not operate effectively and/or safely.
Condition of service brake system	
Condition of parking brake system	
Service brake performance	
Parking brake performance	
Tyres and wheels	
Tyre type	Damaged, worn, substandard or otherwise illegal tyres. Spare wheel, jack and wheel brace (or manufacturers' alternative) not provided and secured.
Tyre condition (including spare)	
Road wheels	
Seat belts	
Mountings	Damaged, worn or incorrectly operating seatbelts. Insufficient seatbelts.
Condition	
General	
Driver's view of the road and mirrors	Loose, damaged, missing or defective mirrors.
Horn	Defective horn.
Exhaust system	Missing, insecure or inadequate heat shield.
Fuel system	Leaks, excessive wear, damaged or insecure pipes, missing filler cap.
Exhaust emissions	Excessive smoke emission.
Body interior	Excessive corrosion/damage, staining, sharp edges.
Luggage space	No separation from passenger seating area.
First aid kit	First aid kit is missing or in a poor/contaminated condition.
Meter - test and seal	Meter not linked to roof sign. Meter not sealed.
Licence plates/door stickers	Damaged/illegible/insecure. Details do not match.
Roof sign and For Hire sign	Insecure, insufficient illumination, wiring defects.
Body exterior	Excessive corrosion/damage, poor repair/paint match, sharp edges.
Doors	Defective locks, windows, door lights, damaged/missing door seals.
Seats	Insecure seats or excessive dirt, stains, holes or tears.
Electrical wiring and equipment	Evidence of overheating. Heavily contaminated with oil.
Speedo	Speedometer inoperative or defective.
Oil and water leaks	Evidence of oil or water leaks including sunroof/windows.

I hereby declare that the above vehicle:
 meets the above standards

*If the test is failed, please notify the relevant licensing office within 24 hours (identified by letter at end of licence number for instance, 100E)


Garage name and address:
 MMC
 SKIPTON
 BD23 2T2

does not meet the above standards
Retest date (if applicable):
Examiner's name: *S. B. M.*
Signature: 
Date of Test: *7/8/24*

- A licensing.cra@northyorks.gov.uk
- B licensing.ham@northyorks.gov.uk
- C taxi.har@northyorks.gov.uk
- D licensing.ric@northyorks.gov.uk
- E taxilicensing.rye@northyorks.gov.uk
- F licensing.sca@northyorks.gov.uk
- G licensing.sel@northyorks.gov.uk

Vehicle testing station number (VTS):
V10285
Authorised examiner number: *K05034*

PASSED 7/8/24



Refusal of MOT test certificate

① Vehicle identification number

ZVW301782885

②a) Registration number ②b) Country of registration

LY63XTK

GB

Make and model

TOYOTA PRIUS

⑤ Vehicle category

④ Mileage

72,200 miles



Driver & Vehicle
Standards
Agency

⑦ Fail

⑥ Repair immediately (major defects)

- Windscreen wiper does not clear the windscreen effectively Nearside [3.4 (b) (ii)]
- Windscreen wiper does not clear the windscreen effectively Offside [3.4 (b) (ii)]

⑥ Repair as soon as possible (minor defects)

- Registration plate lamp insecure Nearside [4.7.1 (c) (i)]

Monitor and repair if necessary (advisories)

- Tyre worn close to legal limit/worn on edge Nearside Front (2mm + bald edges) [5.2.3 (e)]
- Tyre worn close to legal limit/worn on edge Nearside Rear (3mm) [5.2.3 (e)]

③b) Date of the test

07.08.2024

③a) Location of the test

AIREDALE BUSINESS CENTRE, KEIGHLEY ROAD, SKIPTON, BD23 2TZ

⑨ Testing organisation and inspector name

V102805 MMC

B. P. BATTY

MOT test number

8836 5979 5839

To find out about retests, or if you disagree with the test result, see the fees and appeals poster at the vehicle testing station. Alternatively, visit www.gov.uk/getting-an-mot

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Find out about the vehicle's MOT history at www.gov.uk/check-mot-history

Issuer signature



MIDGLEY MOTOR CARS

With us it's personal



AIREDALE BUSINESS CENTRE, SKIPTON, NORTH YORKS, BD23 2TZ, ENGLAND


Telephone 01756 797652
Fax. 01756 790414

The Fisherman Ltd, t/a MMC
Grassington 01756 753136

accounts@midgley.co.uk
www.midgley.co.uk

INVOICE TO

Helli Cars Pink Ladies Ltd



SERVICED VEHICLE

Make Toyota
Model Prius Saloon 1.5 Automatic Petrol

Registration LY63XTK
Chassis No ZVW30-1782885
Engine No
Mileage 72200
Registered 01/11/2022

SERVICE INVOICE

Service No 91584
Invoice No 91292
Date 07/08/2024
Payment
Order No

Your Ref HELLCAR

ADVISORY Next Service Due By 06/02/2025 or MIs Service Advisor Andy Forrest

NSF AND NSR TYRES ON 2MM TREAD -MOT ADVISORY
NS REGISTRATION LAMP INSECURE - MOT ADVISORY

Brief Service Description

WAITING Carry out MOT & Taxi Test booked: 1.00pm

LABOUR WORK CARRIED OUT

	Total	VAT Rate
Line 1	0.00	20.00%
LABOUR TOTAL:		0.00

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
SP26	Wiper Blade 26"	1	15.26	15.26	20.00%
BOSSP16TG	16" WIPER BLADE	1	8.00	8.00	20.00%
PARTS TOTAL:				23.26	

PAID WITH PAYMENTS
Almond

I agree to pay for all work and parts required for the above repairs at your retail charge at the time of collection. I understand that Midgley Motor Cars cannot be held responsible for property left on their premises. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customer's statutory rights. I understand that all parts are covered by manufacturers warranty for 12 months or 12000 miles (whichever occurs 1st) unless stated. MMC will guarantee any work undertaken for a period of 3 months or 3000 miles (whichever is less) from date of repair or completion. However this warranty does not cover fair wear and tear or damage caused by misuse and abuse or failure to have your vehicle serviced to manufacturers recommendations. All goods shall remain the property of the seller until paid for in full.
BACS payments can be made to Yorkshire Bank: Sort Code 05 09 09 Account Number: 17742512.

Sub Total	23.26
MOT: Standard	54.85
Retest	0.00
+ VAT Due	4.65
Invoice Total	82.76
Total Payments	0.00
Total Due	82.76

VAT Analysis	
VAT @ 0% on 54.85 =	0.00
VAT @ 20% on 23.26 =	4.65

Company Reg: 663165

VAT No: 406 0338 89

Date..... Signature.....

Invoice **S & M MOTORS** 31/7/24 59

From **S & M MOTORS**
 KENSINGTON STREET
 KEIGHLEY
 BD21 1PW
 TEL: 01535 603588

VAT Reg'd No. _____

To **PINK LADIES (PRIUS)**



Unit 3, Midland Mills Trading Estate,
 Station Road, Crosshills, Keighley,
 W. Yorkshire, BD20 7DT
Tel: 01535 632211
Mob: 07850 632211
 Email: airdaleautoparts@btconnect.com.

	Amount exclusive of VAT	VAT	NET
	£	£	£
full service	3		
+ wiper			
			37.00

S & M MOTORS
 KENSINGTON STREET
 KEIGHLEY
 BD21 1PW
 TEL: 01535 603588

29/07/29

Part No.	Description	Qty	Rec. Resale Price	Trade Price	Total
A062109	STEEL				
A0122110	FUEL	1	9899	3500	3500
A0122114	SET				
	OWEAST.				
	TORONTO				
	LIBRARY				
				TOTAL	3500
				V.A.T.	200
				TOTAL	4200

204944

Handwritten signature: *W.D. J. ...*

White Copy : INVOICE
 Yellow Copy : ADVICE NOTE
 Pink Copy : OFFICE COPY

VAT TOTAL

V.A.T. No. 173 63 13 13