Appendix D

Driver & Vehicle

Standards

MOT test certificate

Vehicle identification number

ZVW301782885

Registration number

Country of registration

LY63XTK

GB

Make and model

TOYOTA PRIUS

Vehicle category

Mileage

Mileage history

55,428 miles

58,031 miles

14.10.2022



Pass

Date of the test

Second Expiry date

13.09.2023

12.09.2024

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 13.08.2024.

Location of the test

AIREDALE BUSINESS CENTRE, KEIGHLEY ROAD, SKIPTON, BD23 2TZ

(9) Testing organisation and inspector name

V102805 MMC j. t. ayrton

MOT test number

9063 4350 6466

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at **www.gov.uk/mot-reminder** or by telephone on 0300 1239000.





Hackney Carriage and Private Hire Inspection

Local Government (Miscellaneous Provisions) Act 1976 IMPORTANT: Read Standards of Inspection Overleaf

Chassis No: 782 885	Inspection Form Reference:		Vehicle type:
Plate number:	Make and Model: Toyota Mileage: 373	Year of Manufacture:	☐ Hackney carriage
Driver Jame:	Badge Jumber:	No. of Passengers:	Private Hire
All hackney carriage and priva	la Li]

All hackney carriage and private hire vehicles must be maintained to no less than the standards set out in the VOSA publication 'MOT Inspection Manual – Private Passenger and Light Commercial Vehicle Testing', ISBN 978-0-9549352-5-2. Failure to meet the production of the Inspection being failed.

In addition, the inspection should be failed if any of the reasons overleaf apply. Item Tested Pass (V) Fail (x) Reasons for Fallure (see overleaf for guidance) MOT MOT requirements Lighting Equipment Front and rear lamps RHARPASS Headlamps Slop lamps Rear reflectors STA Direction indicators Steering and suspension Steering control Steering mechanism/system Power steering Transmission Wheel bearings Front suspension Rear suspension Shock absorbers Brakes Controls/ABS warning system olaja, Condition of service brake system Condition of parking brake system Service brake performance Parking brake performance Tyres and wheels Tyre type Tyre condition (Including spare) N/S/F Tread Depth N/S/R SPARE O/S/F Road wheels O/S/R Seat belts. Mountings Condition Driver's view of the road and mirrors Horn Exhaust system Fuel system Exhaust emissions Body interior Luggage space First aid kit Meter - lest and seal Licence front and rear plates & doors MRTEK Roof sign & For Hire sign (HC only) THY Body exterior Doors Seals Electrical wiring and eguipment Speedo Oil and water leaks Signage No Smoking signs on display? Advertising on or in vehicle? Yes

Wheelchair accessible vehicles		
Does the vehicle appear to be adapted to be wheelchair accessible?	Yes	(A)
If yes to the above, does the vehicle have a mechanical lift?	Yes	7(6)

If yes to the above, does the vehicle have	a mechanical lift?	Yes Yes	-
Item Tested			
Lighting Equipment	Standards of Inspection - Possible	e reasons for fallure	white)
Front and rear lamps	A CONTRACTOR OF THE PROPERTY O		1. 1.
Headlamps	Lights inoperable or of insufficient intensity.		
Stop lamps	Incorrect bulbs fitted.		
Rear reflectors	Lamps not properly aligned, '		
Direction indicators	Lamp flickers when tapped lightly by hand.		
Steering and suspension			
Steering control			
Steering mechanism/system			
Power steering			
Transmission	Inoperable, worn or faulty steering or suspension.		
Wheel bearings	Jagged edges on steering wheel rim.		
Front suspension	-		
Rear suspension			
Shock absorbers			
Brakes			
Controls/ABS warning system			
Condition of service brake system			
Condition of parking brake system	Any of the systems do not operate effectively and	or safely	
Service brake performance			
Parking brake performance			
Tyres and wheels			
Tyre type	Damaged, worn, substandard or otherwise illegal to	vres	
Tyre condition (including spare)	Spare wheel, jack and wheelbrace (or manufactur	ers' alternative) cot provide	ad an
Road wheels	secured.	ers alternative) not provide	eo an
Seat belts.	Control of the second s	7 1, 7 , 10	
Mountings	Damaged, worn or incorrectly operating seatbelts.		
Condition	Insufficient seatbelts.		
General			
Driver's view of the road and mirrors	Loose, damaged, missing or defective mirrors.		
Horn	Defective horn.		
Exhaust system	Missing, insecure or inadequate heat shield.		
Fuel system	Leaks excessive wear demand an incident		
Exhaust emissions	Leaks, excessive wear, damaged or insecure pipe Excessive smoke emission.	s, missing filler cap.	180
Body Interior	Excessive smoke emission.		
Luggage space	Excessive corrosion/damage, staining, sharp edge	s.	
First aid kit	No separation from passenger seating area.		
Meter - test and seaf	First aid kit is missing or in a poor/contaminated co	andition.	
Licence plates/door slickers	Weter not linked to roof sign. Meter not sealed		
Roof sign and For Hire sign	Damaged/illegible/insecure. Details do not match.		
	Insecure, insufficient illumination, wiring defects.		
Body exterior	Excessive corrosion/damage, poor repair/paint ma	tch, sharp edges	
Doors	Defective locks, windows, door lights, damaged/mi	ssing door cools	
Seats	insecure seats or excessive diff. stains, holds or lo	are	
Electrical wiring and equipment	Evidence of overheating, Heavily contaminated wit	h oil	
Speedo	Speedometer inoperative or defective.	II Oli.	
Oil and water leaks	Evidence of oil or water leaks including sup continu	ndows	
and the second of the second	Control of the contro	ridows.	
			1.
hereby declare that the above vehicle:	*If the test is failed, please notify the relevant	Garage name and add	dress
	licensing office within 24 hours (identified by latter	21	
meets the above standards	end of licence number i.e. 100E)	at	
1			
does not meet the above standards	A licensing.cra@northyorks.gov.uk	77-1:1	
	B licensingleam.ham@northyorks.nov.uk	Vehicle testing station	1
Retest date (if applicable):	C taxi, har@northyorks.gov.uk	number (VTS):	
	D licensing.ric@northyorks.gov.uk	V102805	
Examinera	E taxilicensing.rve@northyorks.gov.uk		
	Filcensing, services, sca@northyorks, asset	Authorised examiner	
Signatura	G licensing.sel@northyorks.gov.uk	number;	
	PASS 57 ALDTONIN 139 23		
Date of Test:	PASS 57 ANDOWN 139 23 SS 628		
12423	901-0		
	22 (58		

Refusal of MOT test certificate

Vehicle identification number

ZVW301782885

Registration number

Country of registration

LY63XTK

GB

Make and model

TOYOTA PRIUS

Vehicle category

Mileage

55,373 miles



® Repair immediately (major defects)

• Rear fog lamp not working Offside Rear [4.5.1 (a) (ii)]

Date of the test

12.09.2023

Location of the test

AIREDALE BUSINESS CENTRE, KEIGHLEY ROAD, SKIPTON, BD23 2TZ

Testing organisation and inspector name

V102805 MMC j. t. ayrton

MOT test number

4965 4234 9734

To find out about retests, or if you disagree with the test result, see the fees and appeals poster at the vehicle testing station. Alternatively, visit www.gov.uk/getting-an-mot

If any of the details are not correct, please contact DVSA by email at **enquiries@dvsa.gov.uk** or by telephone on 0300 1239000.

Find out about the vehicle's MOT history at www.gov.uk/check-mot-history



