

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

②a Registration number

②b Country of registration

GB

Make and model

FORD TOURNEO

⑤ Vehicle category

M1

④ Mileage

386,409 miles

Mileage history

368,156 miles 13.12.2024

336,174 miles 15.12.2023

320,860 miles 14.06.2023

⑦ **Pass**

Monitor and repair if necessary (advisories)

- Suspension component ball joint has slight play Offside Front [5.3.4 (a) (i)]
- Anti-roll bar linkage ball joint has slight play Nearside Front Lower [5.3.4 (a) (i)]
- Steering column top bearing slightly worn [2.2.2 (b)]

⑧ Date of the test

08.10.2025

⑨ Expiry date

07.10.2026

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 08.09.2026.

⑩ Location of the test

CLARENCE DRIVE INDUSTRIAL ESTATE, FILEY, YO14 0AA

⑪ Testing organisation and inspector name

V104626 AUTOMOBILE GARAGE SERVICES LIMITED

MOT test number

16421963 3566

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

Cookies on MOT history service

We use some essential cookies to make this service work.

We'd like to set additional cookies so we can remember your settings, understand how people use the service and make improvements.

[Accept additional cookies](#)

[Reject additional cookies](#)

[View cookies \(/cookie-preferences\)](/cookie-preferences)



Check MOT history

Help us make this service better. Give us your [feedback \(https://www.smartsurvey.co.uk/s/GIZZX?vrn=\[REDACTED\]&make_result=FORD&model_result=TOURNEO&mot_first_used_date=2015-06-30&vehicle_age=3765&mot_expiry_date=2026-10-07&mot_expiry_date_days_left=352&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV\)](https://www.smartsurvey.co.uk/s/GIZZX?vrn=[REDACTED]&make_result=FORD&model_result=TOURNEO&mot_first_used_date=2015-06-30&vehicle_age=3765&mot_expiry_date=2026-10-07&mot_expiry_date_days_left=352&user_satisfaction_banner=0&vehicle_data_origin=MTS&vehicle_type=LGV).

[< Back](#)

FORD TOURNEO

[Check another vehicle \(/\)](#)

Colour
Blue

Fuel type
Diesel

Date registered
30 June 2015

MOT valid until
7 October 2026

[Get an MOT reminder \(https://www.gov.uk/mot-reminder\)](https://www.gov.uk/mot-reminder) by email or text.

[Download test certificates \(/enter-document-reference?registration=YS15ZVX\)](/enter-document-reference?registration=YS15ZVX)

You can [get information corrected on your MOT history \(https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes\)](https://www.gov.uk/getting-an-mot/correcting-mot-certificate-mistakes) (such as mileage or vehicle details) if it's wrong.

[Show all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
8 October 2025

PASS

Mileage
386,409 miles

Test location

▶ [View test location](#)

MOT test number
1642 1963 3566

Expiry date
7 October 2026

Monitor and repair if necessary (advisories):

- **Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**
- **Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**
- **Steering column top bearing slightly worn (2.2.2 (b))**

▶ [What are advisories?](#)

Date tested
8 October 2025

FAIL

Mileage
386,409 miles

Test location

▶ [View test location](#)

MOT test number
8742 5518 9669

Repair immediately (major defects):

- **Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**

Monitor and repair if necessary (advisories):

- **Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))**
- **Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**
- **Steering column top bearing slightly worn (2.2.2 (b))**

▶ [What are defects and advisories?](#)

Date tested
13 December 2024

PASS

Mileage
368,156 miles

Test location

▶ [View test location](#)

MOT test number
1139 1529 6319

Expiry date
14 December 2025

Monitor and repair if necessary (advisories):

- **Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Rear Brake pipe corroded, covered in grease or other material All rear brake pipes (1.1.11 (c))**
- **Front Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are advisories?](#)

Date tested
13 December 2024

Mileage
368,156 miles

MOT test number
7211 4729 5442

FAIL

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**

Monitor and repair if necessary (advisories):

- **Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Rear Brake pipe corroded, covered in grease or other material All rear brake pipes (1.1.11 (c))**
- **Front Oil leak, but not excessive (8.4.1 (a) (i))**

▶ [What are defects and advisories?](#)

Date tested
15 December 2023

Mileage
336,174 miles

MOT test number
6535 0881 8376

PASS

Test location

Expiry date
14 December 2024

▶ [View test location](#)

Monitor and repair if necessary (advisories):

- **Central Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**
- **Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**
- **Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))**
- **Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**

▶ [What are advisories?](#)

Date tested
14 June 2023

Mileage
320,860 miles

MOT test number
1971 5076 8604

PASS

Test location

Expiry date
13 June 2024

▶ [View test location](#)

Monitor and repair if necessary (advisories):

- **Oil leak, but not excessive (8.4.1 (a) (i))**
- **Rear Brake pipe corroded, covered in grease or other material Both. (1.1.11 (c))**

- Brake pipe corroded, covered in grease or other material Both front to back. (1.1.11 (c))
- Central Exhaust silencer outer skin insecure but not likely to become deattached.

▶ [What are advisories?](#)

Date tested
20 December 2022

PASS

Mileage
313,798 miles

Test location

▶ [View test location](#)

MOT test number
7160 4990 8282

Expiry date
19 December 2023

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))
- Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

▶ [What are advisories?](#)

Date tested
15 June 2022

PASS

Mileage
305,594 miles

Test location

▶ [View test location](#)

MOT test number
1769 5513 8623

Expiry date
14 June 2023

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))

▶ [What are advisories?](#)

Date tested
14 June 2022

FAIL

Mileage
305,593 miles

Test location

▶ [View test location](#)

MOT test number
4724 9982 1183

Repair immediately (major defects):

- Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Monitor and repair if necessary (advisories):

- Oil leak, but not excessive (8.4.1 (a) (i))

▶ [What are defects and advisories?](#)

Date tested
13 December 2021

PASS

Mileage
300,765 miles

Test location

▶ [View test location](#)

MOT test number
3140 6372 8598

Expiry date
12 December 2022

Repair as soon as possible (minor defects):

- **Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

Monitor and repair if necessary (advisories):

- **Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**
- **chip in screen**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

▶ [What are advisories?](#)

Date tested
19 July 2021

PASS

Mileage
297,097 miles

Test location

▶ [View test location](#)

MOT test number
4517 9804 5371

Expiry date
18 July 2022

Repair as soon as possible (minor defects):

- **Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**
- **Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**

▶ [What are defects and advisories?](#)

Date tested
11 January 2021

PASS

Mileage
295,974 miles

Test location

▶ [View test location](#)

MOT test number
1072 0296 9020

Expiry date
10 January 2022

Monitor and repair if necessary (advisories):

- **Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))**
- **Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**

► [What are advisories?](#)

Date tested
1 July 2020

PASS

Mileage
291,142 miles

Test location

► [View test location](#)

MOT test number
3203 0319 0627

Expiry date
30 June 2021

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))**
- **Offside Rear Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))**
- **Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**

► [What are advisories?](#)

Date tested
30 June 2020

FAIL

Mileage
291,142 miles

Test location

► [View test location](#)

MOT test number
4965 0662 6327

Repair immediately (major defects):

- **Nearside Front Brake pipe excessively corroded (1.1.11 (c))**
- **Offside Front Brake pipe excessively corroded (1.1.11 (c))**

Monitor and repair if necessary (advisories):

- **Nearside Rear Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))**
- **Offside Rear Brake pipe corroded, covered in grease or other material to hose (1.1.11 (c))**
- **Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**

► [What are defects and advisories?](#)

Date tested
7 October 2019

PASS

Mileage
285,910 miles

Test location

► [View test location](#)

MOT test number
9467 4350 4435

Expiry date
6 October 2020

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**
- **Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**
- **Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
18 April 2019

PASS

Mileage
277,798 miles

Test location

▶ [View test location](#)

MOT test number
2423 4542 1092

Expiry date
17 April 2020

Date tested
17 April 2019

FAIL

Mileage
277,797 miles

Test location

▶ [View test location](#)

MOT test number
8583 8119 0388

Repair immediately (major defects):

- **Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**

▶ [What are defects?](#)

Date tested
3 October 2018

PASS

Mileage
268,255 miles

Test location

▶ [View test location](#)

MOT test number
6550 3140 2501

Expiry date
2 October 2019

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more \(https://www.gov.uk/government/news/mot-changes-20-may-2018\)](https://www.gov.uk/government/news/mot-changes-20-may-2018).

Date tested
16 April 2018

Mileage
222,301 miles

MOT test number
1680 0376 4030

PASS

Test location

▶ [View test location](#)

Expiry date

15 April 2019

Advisory notice item(s)

- **Brake pad warning light is on.**

▶ [What are advisories?](#)

Date tested

12 October 2017

PASS

Mileage

192,170 miles

Test location

▶ [View test location](#)

MOT test number

6485 4061 4109

Expiry date

11 October 2018

Date tested

7 April 2017

PASS

Mileage

138,668 miles

Test location

▶ [View test location](#)

MOT test number

8532 4293 5061

Expiry date

6 April 2018

Date tested

30 September 2016

PASS

Mileage

100,825 miles

Test location

▶ [View test location](#)

MOT test number

3920 2728 0814

Expiry date

29 September 2017

Advisory notice item(s)

- **both rear tyres in poor condition, even tyre wear on inner edge**

▶ [What are advisories?](#)

Date tested

30 September 2016

FAIL

Mileage

100,825 miles

Test location

▶ [View test location](#)

MOT test number

6554 8844 7359

Reason(s) for failure

- **Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**
- **Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**

Advisory notice item(s)

- both rear tyres in poor condition, even tyre wear on inner edge

▶ [What are failures and advisories?](#)

Date tested
30 March 2016

PASS

Mileage
54,790 miles

Test location
▶ [View test location](#)

MOT test number
6379 7968 3648

Expiry date
29 March 2017

Date tested
8 October 2015

PASS

Mileage
24,766 miles

Test location
▶ [View test location](#)

MOT test number
8017 9662 7639

Expiry date
7 October 2016

Advisory notice item(s)

- **Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**

▶ [What are advisories?](#)

Date tested
13 July 2015

PASS

Mileage
1,246 miles

Test location
▶ [View test location](#)

MOT test number
2094 5489 5163

Expiry date
12 July 2016

Check for vehicle recalls

See if FORD TOURNEO [REDACTED] has outstanding recalls

▼ [Show](#)



[Cookies](#) [Terms and conditions](#) [Privacy notice](#) [Accessibility statement](#)

[MOT history API](#) [Service status](#)

Built by the [Driver & Vehicle Standards Agency](#)